



February 2015

**To the Members**

Dear Sirs,

**Oil Spill Response Contract Requirements - Uruguay**

On 20 February 2015, Disposición Marítima N° 149 (the "Regulation") will take effect in Uruguay with the aim of establishing a set of rules governing the requirement for owners, inter alia, to contract with an Oil Spill Response Organisation (OSRO) approved by the Uruguayan Coast Guard. The Regulation has been established under the scope of Uruguayan Law N° 19.012 of 23 November 2012. The intention of this circular is to summarise the key provisions of this Regulation.

The Regulation requires the local agent for any of the following vessels (unless Uruguayan flagged) to conclude an oil spill response clean-up contract with a Uruguayan Coast Guard approved OSRO at least 24 hours before entering a Uruguayan port or an anchorage in Uruguayan waters:

- All tank vessels or barges regardless of size
- All vessels where the Uruguayan authorities have determined that the vessel has a deficiency which could result in her grounding or sinking
- All vessels at anchorage in Uruguayan waters for a period of more than 24 hours
- All vessels engaged in exploration or exploitation of resources in the Uruguayan Exclusive Economic Zone (EEZ).

In case of vessels under the Uruguayan Flag, owners may contract direct with the OSRO.

It is the International Group's understanding that there are currently two approved OSRO's for the purposes of this Regulation, namely Marine Environmental Care Lasimar S.A. (Lasimar) and CINTRA Golantex S.A. (CINTRA). A certificate of coverage provided by one of the two approved OSRO's must be submitted to the local authorities where a vessel falls within the scope outlined above.

The terms of both contracts have been reviewed and both conform with the International Group vessel response plan guidelines.

Contact details for both OSROs are as follows:

L.249

**STEAMSHIP MUTUAL UNDERWRITING ASSOCIATION LIMITED**

Authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and Prudential Regulation Authority  
(Registered in England and Wales – Registration number 105461. PRA and FCA registration number 202548)

**MANAGERS: STEAMSHIP P&I MANAGEMENT LLP**

SPIM is an appointed representative of Steamship Insurance Management Services Limited which is authorised and regulated by the Financial Conduct Authority  
(Registered in England and Wales – Registration Number OC376859. FCA registration number 597046)  
AQUATICAL HOUSE 39 BELL LANE LONDON E1 7LU  
Tel: +44 20 7247 5490 Website: [www.steamshipmutual.com](http://www.steamshipmutual.com)

**GOLANTEX**

Contact: Mr. Ariel Calderón

Email: [ariel.calderon@golantexonline.com](mailto:ariel.calderon@golantexonline.com) and [info@golantexonline.com](mailto:info@golantexonline.com)

24 hours emergency phone numbers:

+598 2900 2326

+598 9531 3772

+598 9531 3672

**LASIMAR**

Contact: Mr. Luis Tabó

Email: [operaciones@mecsa.com.uy](mailto:operaciones@mecsa.com.uy)

24 hours emergency phone number:

+598 9990 2496

The Regulation also requires that, for the abovementioned vessels, the following documentation must be provided to the local authorities:

- Evidence of the vessel's P&I cover. This should be provided by means of the vessel's Certificate of Entry;
- If a tank vessel is carrying more than 2,000 tons of persistent oil in bulk as cargo, the vessel's State certificate issued in accordance with the International Convention on Civil Liability for Oil Pollution Damage, 1992;
- A certificate of cover, provided by the OSRO, in the format required by the Regulation in order to evidence that the owner has entered into an OSRO contract with either of the two contractors mentioned above.

It is important therefore that owners with vessels that fall within the scope of these requirements renew their P&I cover sufficiently in advance of 20 February in order to ensure compliance with the Regulation. In particular, the vessel's local agents should be able to provide the required documents no less than 24 hours prior to requesting authorisation for the vessel to anchor or operate in Uruguayan waters.

The International Group will continue to review the situation, and further update to Members will be provided in due course, where necessary.

Members should however work on the basis that the Regulation, together with the accompanying requirement to contract with an approved OSRO, will become effective on 20 February 2015, and should make contact with their Club accordingly.

All Clubs in the International Group of P&I Clubs have issued similar circulars.

Yours faithfully,

**THE STEAMSHIP MUTUAL UNDERWRITING  
ASSOCIATION LIMITED**

**STEAMSHIP MUTUAL UNDERWRITING ASSOCIATION LIMITED**

Authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and Prudential Regulation Authority

(Registered in England and Wales – Registration number 105461. PRA and FCA registration number 202548)

**MANAGERS: STEAMSHIP P&I MANAGEMENT LLP**

SPIM is an appointed representative of Steamship Insurance Management Services Limited which is authorised and regulated by the Financial Conduct Authority

(Registered in England and Wales – Registration Number OC376859. FCA registration number 597046)

AQUATICAL HOUSE 39 BELL LANE LONDON E1 7LU  
Tel: +44 20 7247 5490 Website: [www.steamshipmutual.com](http://www.steamshipmutual.com)